WILLIAMS ENVIRONMENTAL SERVICES, INC.



September 17, 1990

RECEIVED N.C. Dept. NRCD

SEP 24 1990

Mr. Andrew Raring
Regional Groundwater Supervisor
State of North Carolina
Department of Environmental Health and Natural Resources
8025 Northpoint Boulevard, Suite 100
Winston-Salem, North Carolina 27106

Winston-Salem Regional Office

Re:

Tank Removal Assessment

WES Project No. 1100-023-120

Dear Mr. Raring:

Williams Environmental Services, Inc. (WES) was retained to perform a tank removal assessment for (Land-O-Sun (Pet Dairy)) located at 544 Chapel Hill Road in Burlington, North Carolina. One 1,000 gallon gasoline tank was removed recently from this site which is now "Carolina Cable Contractors". This tank's approximate location is shown in Figure 1.

WES arrived on the site on September 5, 1990 and pulled this second tank which was discovered after our June 13, 1990 visit, which involved pulling the first tank. This second tank was discussed with Mr. Tom Sally of your office. Again, there was no groundwater encountered and soil surrounding the tank was relatively clean. No holes were found in the tank and no strong hydrocarbon odors were present. Soil samples were hand carried to Law & Company's laboratory by WES's geologist to expedite the results. All three samples were tested for BTEX and TPHC. Sample number G-11 was tested for PH, which ran 5.2. Analytical results are summarized in Table 1, and are included as an attachment.

If you should have any questions, or if I can be of further assistance, please do not hesitate to call.

Sincerely,

Williams Environmental Services, Inc.

16. Miell

David A. Mitchell, P.E., P.G.

Environmental Geologist

DAM:sle Enclosures


TABLE 1


LABORATORY RESULTS


GASOLINE TANK PIT

<u>MATRIX</u>	<u>ANALYSIS</u>	RESULTS			
SOIL	ТРНС	ND			
SOIL	TPHC	ND			
SOIL	TPHC	ND			
SOIL	BTEX	ND			
SOIL	BTEX	ND			
SOIL	BTEX	ND			
SOIL	PH	5.2			
	SOIL SOIL SOIL SOIL SOIL SOIL	SOIL TPHC SOIL TPHC SOIL TPHC SOIL BTEX SOIL BTEX SOIL BTEX			

ND - NON DETECTED







EXPLANDATION

Law & Company

CONSULTING AND ANALYTICAL CHEMISTS

1763 MONTREAL CIRCLE TUCKER, GEORGIA 30084 (404) 934-8200

Chemical Report

9/17/90

Number: 918973 Received: 9/12

28660 Harmon Engineering Assoc., Inc 2066 W. Park Place, Suite A-1 Stone Mountain 30087

Description: Project Land O Sun, Burlington, Sample G-10

рн	5.2	
Total Petroleum Fuel Hydrocarbons	<10	ppm
Benzene	'	
Toluene	<10	ррВ
Ethyl Benzene	<10	рpВ
Xylene	<10	ррВ

Respectfully submitted, LAW & COMPANY

BY Thomas E. Fanty

Law & Company

CONSULTING AND ANALYTICAL CHEMISTS

1763 MONTREAL CIRCLE
TUCKER, GEORGIA 30084
(404) 934-8200

Chemical Report

9/17/90

Number: 918974 Received: 9/12

28660

Harmon Engineering Assoc., Inc 2066 W. Park Place, Suite A-1 Stone Mountain 30087

Description: Project Land O Sun, Burlington, Sample G-11

Total Petroleum Fuel Hydrocarbons	<10	mqq
Benzene	<10	Ваа
Toluene		ррВ
Ethyl Benzene		
Xylene	<10	ppB

Respectfully submitted, LAW & COMPANY

BY Thomas E. Lantz

Law & Company

CONSULTING AND ANALYTICAL CHEMISTS

1763 MONTREAL CIRCLE
TUCKER, GEORGIA 30084
(404) 934-8200

Chemical Report

9/17/90

Number: 918975 Received: 9/12

28660

Harmon Engineering Assoc., Inc 2066 W. Park Place, Suite A-1 Stone Mountain 30087

Description: Project Land O Sun, Burlington, Sample G-12

Total Petroleum Fuel Hydrocarbons	<10	ppm
Benzene	<10	ррВ
Toluene	<10	ррВ
Ethyl Benzene	<10	ppB
Xylene	<10	ррВ

Respectfully submitted, LAW & COMPANY

BY Thomas E. Fanty

Chain of Custody Record

HEAMQUISHED BY (Signature)	Was Shipping Container Intact When Received By Lab? Yes					9/6	- 1	6-11	CILID NO.			Tand little		1100-023-12	Project Name / Project No.
DATE / TIME	act When Re					2	,	06,	1			6 5		0	
S. S	ceived		-			"	"	10 AM	TIME	50	2	STONE			1
RECEIVED BY (Sign	K					" "	11 41	Evennera, Mc.	LOCATION	COLECTOR	<u> </u>	Mount	() = NG/A	-	インローローへ
WERE ALL INDIVIDUAL SAMPLE SEALS INTACT? YES NO IF NO, INDICATE SAMPLE NUMBERS ON WHICH SEALS WERE BROKEN AT TIME OF RECEIPT. Harmon Engineering Associates, Inc.	NoInitialsTotal No. of Containers						2 4 4 2	BR. CLAYEY SILT THEH & BIEX	SAMPLE TYPE/DESCRIPTION ANALYSIS REQUIRED	METHODS METHODS		CK PLACE	6 ASSU	٠ اـ	

(010)

6450LIN)5

なう
ア
ン

David A. Mitchell Environmental Geologies

2086 West Park Placo Suite A-1 Stone Mountain, GA 20087 Phone (404) 450-3065 FAX (404) - A 7 • O

Consulting Engineers & Scientists